

■写真

令和8年4月分 ✓

受付番号 (通報日)	着手前	完了
NO.2 ✓ (4/5) ✓	 A photograph showing a road surface with a small hole or depression. A wooden fence is visible on the right side of the road.	 A photograph showing the same road surface after repair, with the hole filled and the surface smoothed. A shadow is cast on the road to the right. ※路面補修 ✓
NO.17 ✓ (4/17) ✓	 A close-up photograph of a road surface with a large, irregular hole and significant cracking. A circular manhole cover is visible in the background.	 A close-up photograph of the same road surface after repair, showing a smooth, filled-in area next to a blue and white striped curb. ※路面補修 ✓
NO.23 ✓ (4/26) ✓	 A wide-angle photograph of a residential street. A red arrow points to a small hole on the road surface, which is also circled in red. A red arrow points to a small hole on the road surface, which is also circled in red.	 A close-up photograph of the road surface after repair, showing a smooth, filled-in area. ※路面補修 ✓