

■写真

令和8年1月分

受付番号 (通報日)	着手前	完了
NO.2 (1/4)	 A photograph showing a road construction site before completion. A concrete curb is being installed along the edge of the road, with some yellow plants and orange traffic cones visible.	 A photograph showing the same road construction site after completion. The concrete curb is fully installed, and the area is clean with some yellow plants. Two red and white striped safety posts are placed along the curb. <p data-bbox="885 790 1118 831">※安全施設復旧</p>
NO.5 (1/7)	 A photograph showing a road surface before repair. The surface is dark and appears to be made of asphalt or concrete, with some shadows cast across it.	 A photograph showing the same road surface after repair. The surface is now light-colored and appears to be made of gravel or crushed stone, with some shadows cast across it. <p data-bbox="885 1346 1054 1386">※路面補修</p>
NO.7 (1/12)	 A photograph showing a curve mirror before adjustment. The mirror is mounted on a pole and is tilted downwards, reflecting the ground and some buildings.	 A photograph showing the same curve mirror after adjustment. The mirror is now tilted upwards, reflecting the sky and some buildings. <p data-bbox="885 1899 1251 1939">※カーブミラー向きの調整</p>