

■写真

令和6年4月分

受付番号 (通報日)	着手前	完了
NO.5 (4/12)		 ※陥没処理
NO.12 (4/18)		 ※カーブミラー庇撤去
NO.22 (4/29)		 ※穴埋め処理