

# ■写真

令和7年3月分

| 受付番号<br>(通報日) | 着手前                                                                                                                                                                                                                                                                       | 完了                                                                                                                                                                                                                                                                                       |
|---------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| NO.1<br>(3/3) |  A photograph of a residential street before road repair. The road surface is asphalt with a green-painted section on the left side. A metal fence runs along the left side of the road. |  A photograph of the same residential street after road repair. The road surface is now smoother and the green-painted section is more uniform. The metal fence is still visible on the left.<br>※路面補修 |
| NO.2<br>(3/3) |  A photograph of a side ditch area before repair. A brick wall is on the left, and a black metal gate is partially open. A white car is parked in the background.                       |  A photograph of the same side ditch area after repair. The ground is now paved with concrete, and the black metal gate is closed. A white car is still visible in the background.<br>※側溝補修           |
| NO.4<br>(3/8) |  A photograph of a convex mirror mounted on a pole. The mirror is tilted downwards and reflects a view of the road below.                                                              |  A photograph of the same convex mirror after adjustment. The mirror is now tilted upwards and reflects a view of the road above, showing a house and a car.<br>※カーブミラー向きの調整                        |