

■写真

令和5年8月分

受付番号 (通報日)	着手前	完了
NO.4 (8/1)		 ※カーブミラー向きの調整
NO.8 (8/2)		 ※外側線の復旧
NO.27 (8/15)		 ※陥没処理