

# 写真

令和8年5月分

| 受付番号<br>(通報日)      | 着手前                                                                                                                                                                                                                      | 完了                                                                                                                                                                                                    |
|--------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| NO.8・9<br>(5/7)    |  A photograph showing a road surface with a dark, irregular patch, likely a pothole or damaged asphalt, before repair work.             |  A photograph showing the same road surface after repair, with the dark patch filled and the surface smoothed.      |
|                    |                                                                                                                                                                                                                          | ※路面補修                                                                                                                                                                                                 |
| NO.14<br>(5/11)    |  A photograph showing a road edge with a damaged white guardrail and a red and white striped traffic cone, indicating a safety hazard. |  A photograph showing the same road edge after the guardrail has been replaced and the area cleaned up.            |
|                    |                                                                                                                                                                                                                          | ※安全施設復旧                                                                                                                                                                                               |
| NO.17・18<br>(5/12) |  A photograph showing a road surface with a small, dark, irregular patch, likely a pothole or damaged asphalt, before treatment.      |  A photograph showing the same road surface after treatment, with the dark patch filled and the surface smoothed. |
|                    |                                                                                                                                                                                                                          | ※陥没処理                                                                                                                                                                                                 |